Product information - BMW brake pads | HELLA

Product information

BMW brake pads

8DB 355 012-321 / 8DB 355 015-601

Changed brake pads

Due to a change in the serial equipment carried out by the vehicle manufacturer BMW, the following article allocation has been adapted as described in the following.

Brake pad 8DB 355 012-321 / T1596 will be replaced by brake pad 8DB 355 015-601 / T2029.

Vehicle allocation

8DB 355 015-601 / T2029

E84, E89, E90, E91, E92, E93

Note:

Please observe the respective product allocations in the catalog.

Mounting instructions

The difference between both brake pads is the missing retaining spring (A) on the brake pad 8DB 355 015-601 / T2029 on the fist side. The missing retaining spring does not have any influence on the comfort conduct of the brake pad.

