



# MCC Smart forfour - headlamps permanently on

|                     |                                                                                       |
|---------------------|---------------------------------------------------------------------------------------|
| Data sheet          |                                                                                       |
| Manufacturer        | MCC                                                                                   |
| Model               | Smart forfour                                                                         |
| Year of manufacture | 2015 - 2019                                                                           |
| Symptoms            | Headlamps permanently light up, switching between low beam and high beam not possible |

## Important safety note

## MCC Smart forfour - headlamps permanently on, switching between low beam and high beam not possible

If the headlamps on this vehicle are permanently on and / or it is not possible to switch between low and high beam, the cause could be a faulty multifunction switch. In addition, the error may be stored in the control unit. In order to remedy the situation, the multifunction switch should be checked and, if necessary, replaced and the error memory deleted.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.