



Vauxhall Adam - engine cuts out

Data sheet

Manufacturer	Vauxhall
Vehicle model	Adam
Year of manufacture	2014 - 2018
Symptoms	Engine cuts out after cold start or engine cuts out when disengaging the clutch in coasting mode

Important safety note

Vauxhall Adam - engine cuts out

The following symptoms may occur in the above-mentioned vehicles due to faulty engine control unit software:

- Engine cuts out after cold start
- Engine cuts out when disengaging the clutch in coasting mode

In an effort to rule out other causes, check all possible system components and read out/delete the fault memory.

If no errors are identified, update the engine control unit software. We advise to contact an Vauxhall workshop for this purpose.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.