

Citroen C4 - Hand-brake lever releasing unexpectedly | HELLA

Citroen

C4

All models up to model year 04/2007

Hand-brake lever releasing unexpectedly

In some vehicles, the hand-brake lever may release unexpectedly after being engaged.

This is due to worn components in the locking mechanism.

Repair note

It is not possible to replace the defective components individually. If damaged, the entire hand-brake lever must be replaced.

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.