Bulletin



© Hella KGaA Hueck & Co., Lippstadt Q1 / 2013

Mercedes W210

Type: 210.###(except 210.072)#A to 133401

Type: 210.### #J to 021795

with engine: 104,111,112,113,119,/602,604,605,606,611,612,613,

Faulty starter, corroded / water damage

Complaint:

There are – starter defective – failures in the above vehicles

Cause:

Corrosion in the starter electrics must be analysed as a possible cause of the fault. This may be the result of "misdirected" water drain.

Solution:

- Remove, install and replace the starter.
- !!! Check the water drain of the water collector in the event of any starter damage. [if necessary, install modified water drain (2108320125)].

Bulletin

