

OPEL Astra J - Le voyant de l'alternateur s'allume | HELLA

OPEL

Astra J

Année modèle : 2010 - 2012

Code défaut B1517

Le voyant de l'alternateur s'allume

Sur les véhicules cités ci-dessus, il se peut que le voyant de l'alternateur s'allume, bien que la tension de la batterie et de l'alternateur soient correctes. Simultanément le code d'erreur B1517 (03) apparaît dans le calculateur. Ceci est équivalent à « Tension batterie sous la valeur de consigne».

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.