

Renault, Citroen, Peugeot - Poor braking with the driving brake | HELLA


Renault, Citroen, Peugeot

All models with drum brakes

Poor braking with the driving brake and parking brake.

Malfunction of the automatic adjusting device on the rear axle drum brake system.

If one of the errors listed above occurs on these vehicle models, the cause may stem from a vertically mounted safety clip on the brake shoe.(Fig.1)





Please remember to always follow the general assembly instructions for installing and removing drum brakes and other special installation instructions from the brake pad or vehicle manufacturer in this regard.

