

# Fiat Seicento - Irregular engine running | HELLA

**Fiat Seicento**

**All models with 899ccm engine**

**Poland plant**

**Irregular engine running**

**Irregular engine running**

The front right ground cable connection may be faulty if irregular engine running is identified in the above vehicles and there is no entry in the control unit's event memory. Hardening of the insulation material can lead to the cable breaking in the area of the tubular cable lug.

The ground point is located on the right wheel housing behind the headlight in the driving direction.

