

# Mercedes Benz Vito 2 - Faulty function: Rear window wiper | HELLA

**Mercedes Benz**

**Type: 639**

**Model year: from 2003**

**All models**

**Faulty function: Rear window wiper**

**Faulty function: Rear window wiper**

**Faulty function: Rear window wiper**

If one or more of the above problems are identified on this vehicle model, this may be associated with corrosion of the multi-function relay.

