

Opel Corsa D - Med manuelt klimaanlæg | HELLA

Opel Corsa D Årgang: 2007 - 2009 Med manuelt klimaanlæg
Blæsermotoren virker ikke Hvis blæsermotoren ikke virker i ovennævnte modeller, kan årsagen være en defekt stikforbindelse ved formodstanden. Det gælder modeller med manuelt klimaanlæg og følgende stelnumre: indtil **W0L0SDL6894298980 (Fabrik Zaragoza)** indtil **W0L0SDL0896118216 (Fabrik Eisenach)** Fejlen afhjælpes på følgende måde: Afmonter handskerummet Fjern luftkanalen i fodrummet Træk stikket af formodstanden Kontroller stikket ved hjælp af et spejl Hvis stikket er beskadiget: Udskift formodstanden, og monter et reparationssæt til stikket (begge dele leveres af de autoriserede forhandlere) Foretag en funktionstest Monter luftkanal og handskerum

Corsa D

Model year: 2007 - 2009

With manual air conditioning system

Interior blower not working

If the interior blower fails in one of the vehicles listed above, this may be caused by a faulty plug connection on the series resistor.

Vehicles with a manual air conditioning system and the following chassis number:

up to W0L0SDL6894298980 (Zaragoza plant)

up to W0L0SDL0896118216 (Eisenach plant)

Proceed as follows to rectify the problem:

- Take out the glove box
- Remove the air duct in the footwell
- Take the plug off the series resistor
- Check the plug using a mirror
- If the plug is damaged: Replace the series resistor and use a repair plug set (both available from the authorized dealer)

- Perform functional test
- Install air duct and glove box