

Opel Corsa D - Vibrations and noises | HELLA

Opel

Corsa D

Engine code:

Z10XEP, Z12XEP, Z14XEP, Z13DTJ

Model year 2007–2011

Vibrations and noises

on the front axle

If the above fault occurs, it may be associated with the OE brake linings in the front axle. These vibrations or noises mainly occur when a light braking force is applied in urban traffic.

In this case, the brake linings must be checked as part of the diagnostics process and replaced if necessary.

Note

The vehicle manufacturer supplies modified brake linings

for brake disks measuring 257 x 22 mm in this case.

OE part number: 93169254

HELLA reference part number: 8DB 355 012-831