

# **CITROEN Berlingo - Défaillance du feu de croisement | HELLA**

**CITROEN**

**Berlingo**

**Année Modèle : de 2002 à 2008**

**Défaillance du feu de croisement**

Struktur

Basen

Elemente

Fläche  
Abgrenzung

visuelle  
Unterstützung

Technische  
Darstellung


Einmalige Identität,  
das Spring.

## Sicherungen und Installationsmaterial

Das aktuelle Sortiment.



Always for the  
auto-oly product

4.4 Corrugated pipes	Nominal ID	Inner diameter	Outer diameter	Material	Contents (pcs)	Part number	WPE (pcs)
<b>Slotted corrugated pipes</b> 	7,5	6,7	10	PP	50	▶ 8JR 177 882-002	50
	10	9,9	13	PP	50	▶ 8JR 177 882-012	50
	13	12,7	15,8	PP	50	▶ 8JR 177 882-022	50
	17	16,6	21,2	PP	50	▶ 8JR 177 882-032	50
	22	21,3	25,4	PP	50	▶ 8JR 177 882-042	50
	26	25,8	31,2	PP	50	▶ 8JR 177 882-052	50
	37	36	42,4	PP	25	▶ 8JR 177 882-062	25

### Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.