

Nissan Qashqai - Performance de freinage insuffisante | HELLA

Nissan

Qashqai

Modèle: J10 et NJ10

Année de fabrication : 08.2010 - 02.2011

Repair notes

In the event of customer complaints, special attention should therefore be paid to these components during fault diagnosis. Material fatigue may in this case result in expansion or leakage of the brake hose, and in the worst-case scenario in failure of the braking system.

Procedure:

- Check brake hoses und lines for routing, condition and leak tightness.
- Remove and replace faulty parts.

In this context please observe the repair and maintenance notes provided by the vehicle manufacturer.