

Seat Ibiza - Le voyant moteur s'allume | HELLA

Seat

Ibiza (6J)

Année de fabrication : à partir de 2009

Moteur: 1,6 TDI

Radiateur de recyclage de gaz d'échappement

Le voyant moteur s'allume

Si la mémoire des défauts des véhicules mentionnés ci-dessus contient des messages en rapport avec le recyclage des gaz d'échappement, la cause peut en être un radiateur de recyclage de gaz d'échappement défectueux.



· Calaminage interne



Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.