

Citroën Berlingo - La luz de cruce falla | HELLA

Citroën

Berlingo

Fabricados entre 2002 y 2008

Failure of the low beam

Struktur

Basen

Stämme

Flächen-
abgrenzung

Individuelle
Lichtgestaltung

Technische
Lösungen


Einmalige Ideen,
für jeden.

Sicherungen und Installationsmaterial

Das aktuelle Sortiment.



Always for the
automotive product

4.4 Corrugated pipes	Nominal ID	Inner diameter	Outer diameter	Material	Contents (pcs)	Part number	WPE (pcs)
Slotted corrugated pipes 	7,5	6,7	10	PP	50	▶ 8JR 177 882-002	50
	10	9,9	13	PP	50	▶ 8JR 177 882-012	50
	13	12,7	15,8	PP	50	▶ 8JR 177 882-022	50
	17	16,6	21,2	PP	50	▶ 8JR 177 882-032	50
	22	21,3	25,4	PP	50	▶ 8JR 177 882-042	50
	26	25,8	31,2	PP	50	▶ 8JR 177 882-052	50
	37	36	42,4	PP	25	▶ 8JR 177 882-062	25

Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.