

Toyota Auris, Corolla - Geklapper bij de wielrem van de vooras | HELLA

Toyota

Auris, Corolla

Alle modellen met 15-inch voorrem

Geklapper bij de wielrem van de vooras

Bij de bovengenoemde voertuigmodellen kan bij het rijden over ongelijke wegen geklapper optreden bij de wielrem van de vooras. Als het rempedaal licht wordt ingedrukt, verdwijnt het geluid.

Dit probleem kan worden veroorzaakt door de constructie van de remklauwhouder. De autofabrikant biedt voor deze gevallen gewijzigde remklauwhouders met gewijzigde geleidepenen en stofhoezen.

Afstelmaatregel

Visuele controle uitvoeren. Remsysteem van de vooras op beschadigingen, correcte werking, overmatige vervuiling of slijtage controleren. De wielrem zo nodig voor een verdere controle deels demonteren. Als er geen gebreken kunnen worden vastgesteld, moeten de remklauwhouders worden gecontroleerd en zo nodig door de gewijzigde onderdelensets worden vervangen.

De ombouw is herkenbaar aan de gewijzigde geleidepen met bus. (Afbeelding)

Neem in dit verband ook altijd de onderhouds- en reparatie-instructies van de voertuigfabrikant in acht!



Opmerking

The following vehicles are affected.

Model codes: NDE180, NRE180, NRE185, WWE185, ZRE181, ZRE182, ZRE185 and ZWE186

To remedy the defect, the following OE spare parts have been offered by the vehicle manufacturer as part of a corrective measure:

- Brake calliper carrier 47721-09560

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only. Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.