

Lancia Ypsilon - Vibrations and noises on the front axle

Lancia Ypsilon (843)

Engine code: all models

Model year: 2003 - 2011

Vibrations and noises on the front axle

If the above-mentioned fault is detected, its cause can often be found in connection with the brake pads of the front axle. These vibrations or noises mainly occur when driving takes place on uneven roads and surfaces.

This may lead to the brake pads installed ex-factory knocking against the brake caliper carrier as a result of the construction. If the noise is suppressed by a slight braking action, in this case the brake pads must be checked as part of a diagnostic action and renewed where applicable.

Note

In the scope of a corrective action, modified brake pads have been offered by the vehicle manufacturer.

Engine code: 169 A4000 and 188 A4000

OE part number: 71741261

Engine code: 350 A1000 and 843 A1000

OE part number: 71741260