




## Audi A5 – SCR Sistemi Ar#zas#

Data sheet	
Manufacturer	Audi
Vehicle model	A5
Engine	3.0 TDI
Engine code	CKVC
Year of manufacture	2011 to 2017
Symptoms	Information on the malfunctioning of the SCR system in the instrument cluster
Recommended HGS tool	megamacsX

### Important safety information

**Veri sayfas#ÜreticiAudiModelA5Motor3.0 TDIMotor koduCKVCModel y#l#2011 ila 2017BelirtiGösterge panelinde SCR sistemi ar#zas#yla ilgili bir uyar#Önerilen HGS Arac#megamacsX**

Önemli güvenlik uyar#s# Çal##malar#nda araç servislerine profesyonel destek sa#lamak için, teknik bilgiler ve uygulamaya yönelik ipuçlar# HELLA taraf#ndan derlenmi#tir. Bu web sitesinde sa#lanan bilgiler, yaln#zca uygun #ekilde e#itilmi# uzman personel taraf#ndan kullan#lmal#dır.

 **Please note**

Please always follow the repair instructions from the vehicle manufacturer when carrying out such work!