



# BMW i3 – Bilgi-E#lence Sistemi Ar#zas#

## Important safety information

## Ayr#ca bu da ilginizi çekebilir

Bu doküman içeri#inin sonradan bas#lmas#na, da##t#lmas#na, ço#alt#lmas#na, herhangi bir #ekilde kullan#lmas#na ve iletilmesine, al#nt# #eklinde dahi olsa, yaln#zca aç#k yaz#l# onay#m#z ve kaynak belirtmek kayd#yla izin verilir. #ematik #ekiller, resimler ve tan#mlar yaln#zca doküman metninin temsili ve aç#klanmas#na hizmet etmektedir ve montaj veya tasar#m için temel al#namaz. Tüm haklar# sakl#d#r.

## Please note

Please always observe the maintenance and repair notes provided by the vehicle manufacturer when carrying out such work and checks!

This fault profile may also occur in other vehicle models with comparable equipment variants.

Reprinting, distribution, reproduction, exploitation in any form whatsoever or disclosure of the contents of this document, even in part, is prohibited unless our express permission has been obtained in writing beforehand and the source is stated. The schematic illustrations, pictures and descriptions are provided for explanatory purposes and are only intended as a visual supplement to the document text, so they cannot be used as the basis for installation or assembly work. All rights reserved.