



Vauxhall Astra - fuel gauge faulty

Data sheet

Manufacturer	Vauxhall
Vehicle model	Astra K
Engine	All models
Year of manufacture	2015 -
VIN	G8000000 - G8060668
Symptoms	Faulty fuel gauge

Important safety note

Fuel gauge does not display the correct tank content

On the vehicles mentioned above, the fuel level display on the instrument cluster may be displayed incorrectly, so it is possible that the tank is full but a lower fill level is displayed.

Vehicles in the range of the following chassis numbers are affected: G8000000 - G8060668

A 'software weakness' could be causing the problem.

To remedy the situation, check whether a software update is available for the vehicle. An Vauxhall dealer should be contacted for this.



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.