

Vauxhall Meriva B - Loss of coolant | HELLA

Vauxhall

Meriva B

Model year: 2010 - 2012

With air-conditioning system

Loss of oil from the compressor/

Loss of coolant

The above vehicles can experience a compressor leakage. This is mostly noticeable by escaping oil/dye. To fix this problem, the compressor must be exchanged with a modified version:

Old part number: Corresponding new replacement part number:

13 271 266 13 395 693

13 271 267 13 395 694

13 271 268 13 395 695

13 271 269 13 395 696

13 271 264 13 395 696

Vehicles from the 2012 model year including chassis number B4408747 use factory modified compressors.